
Issued to:	Location of equipment:	Issued by:			
GROUNDTRAX SYSTEMS LTD STATION YARD RIPLEY HARROGATE	GROUNDTRAX SYSTEMS LTD STATION YARD RIPLEY HARROGATE		Lloyds British a division of Speedy Asset Services Ltd Brunel Industrial Estate Blyth Road	BRITISH	
			Harworth	Report no:	PRJ-117152/004
			DN11 8QA	Your Order no:	2750
		Tel:	01302 751267	Our Job no:	PRJ-117152
HG3 3BA	HG3 3BA			Sheet no:	1 of 1

## Report of Test of Lifting Plant and Equipment

Identification Mark		Details of Test and Thorough Examination						
Identification Mark of the Equipment:	Description of Equipment		Safe Working Load: (Specify Units)	Proof Load Applied: (Specify Units)	Additional/Examination/Standards	Date of Test and Examination:		
BATCH TEST 4	STANDARD PVC CELLPAVE HD MAT	2	N/A	21t EMPTY	REPORT OF COMPRESION	14/11/22		
	600MM X 400MM X 75MM			22t EMPTY	TEST			
				26t EMPTY	POINT LOAD TESTS USING			
	SAMPLE TESTED EMPTY THEN TESTED FILLED WITH				250MM DIA DISC TO SIMULATE			
	14MM ANGULAR LIMESTONE GRAVEL			25t FILLED	WHEEL LOADING 0.0491m <sup>2</sup>			
				30t FILLED	RESULT: 26t EMPTY DEFORMED			
				40t FILLED	EQUIVALENT TO 529.62tm <sup>2</sup> LOADING			
					40t FILLED EQUIVALENT			
					TO 814.8tm <sup>2</sup> LOADING			

TESTED SAMPLE NOW SCRAPPED



Registered Office: Speedy Asset Services, 16 The Parks, Newton Le Willows, WA12 0JQ Company Registration No: 6847930 VAT Reg. No: GB 151 629570